




A mm (inch)



B




C




D

JP1 <table border="1"> <tr><td>3</td><td>U...</td></tr> <tr><td>2</td><td>I...</td></tr> <tr><td>1</td><td></td></tr> </table>	3	U...	2	I...	1		JP4 <table border="1"> <tr><td>3</td><td>U... 0...10 V</td></tr> <tr><td>2</td><td>I... 0...20 mA</td></tr> <tr><td>1</td><td></td></tr> </table>	3	U... 0...10 V	2	I... 0...20 mA	1	
3	U...												
2	I...												
1													
3	U... 0...10 V												
2	I... 0...20 mA												
1													
<table border="1"> <tr><td>3</td><td>I...</td></tr> <tr><td>2</td><td></td></tr> <tr><td>1</td><td></td></tr> </table>	3	I...	2		1		<table border="1"> <tr><td>3</td><td>U... 2...10 V</td></tr> <tr><td>2</td><td>I... 4...20 mA</td></tr> <tr><td>1</td><td></td></tr> </table>	3	U... 2...10 V	2	I... 4...20 mA	1	
3	I...												
2													
1													
3	U... 2...10 V												
2	I... 4...20 mA												
1													



i



G: AC 24 V 50-60 Hz, DC +24 V $\pm$ 10%

G0: AC 0 V, DC -24 V

U... DC 0(2)...10 V

I... DC 0(4)...20 mA



www.vectorcontrols.com

