



A mm (inch)



B

⏻	On/Off Key	Change operation mode Exit from parameter menu
⬆	Up Key	Increase setpoint Select parameter
⦿	Option Key	Select display Enter in parameter menu
⬇	Down Key	Decrease setpoint Select parameter

C Display exchange



D For SxC2-Series

