





B

	On/Off Key	Change operation mode Exit from parameter menu
	Up Key	Increase setpoint Select parameter
	Option Key	Select display Enter in parameter menu
	Down Key	Decrease setpoint Select parameter


C

Display exchange


1.



2.



3.



4.

