






A mm (inch)



B




C




D

24V AC/DC G0 = M = GND




E


Master-Slave (max. 8x TCX2, 1x OPX-VC)



i



i



📖

