




A mm (inch)



B




C



D

JP1	JP2
3 ○ U...	3 ○ U... 0...10 V
2 ○ I...	2 ○ I... 0...20 mA
1 ○	1 ○
3 ○ U...	3 ○ U... 2...10 V
2 ○ I...	2 ○ I... 4...20 mA
1 ○	1 ○




G: AC 24 V 50-60 Hz, DC +24 V $\pm 10\%$

G0: AC 0 V, DC -24 V

U... DC 0(2)...10 V

I... DC 0(4)...20 mA



www.vectorcontrols.com

